71377, In-Car Mounting Bracket for BMW X5 E53 – 2001 – Not Sat Nav

- Remove the radio volume control knob
- Utilising a narrow flat bladed screwdriver, insert the tip into the guide hole below the control knob's retainer
- Twist through 90 degrees to allow the side of the head unit to be pulled forwards and out
- Remove the two torx screws on the driver's side of the radio unit itself
- Locate the bracket with these two screws
- Refit the radio unit and volume control knob

www.co-star.co.uk **t: +44 (0) 1423 340066** **e: sales@co-star.co.uk**

Co-star will not be liable for any damage caused when fitting the bracket